| Scope of | Work for Property Loc | cated at: | 3938 North 42nd Street | |
|------------------|--------------------------------------|--------------------------|--|----------|
| | Property is: Single Fan | nily X Duplex | Other | |
| Date: | 4/7/2010 | <u></u> | | |
| take no respo | onsibility for problems discovered a | after the inspection dat | s. The City of Milwaukee, the Redevelopment Authority, and their repate, or for omissions through error or oversight. The list does not necesteral Block Grant or HOME programs. | |
| Exterior | Condition Report | | | |
| Location Site | Required Work Landscaping | n/a X Yes | Note/Comments Self Help \$ | Cost |
| | Steps/Handrails | n/a χ Yes | \$ | |
| | Service walks | n/a X Yes | \$ | |
| | Fencing | n/a Yes X | Repairs \$ | 600.00 |
| | Parking | n/a X Yes | \$ | |
| | Retaining walls | n/a X Yes | \$ | |
| | Other | n/a X Yes | \$ | |
| | Other | n/a X Yes | \$ | |
| Garage | Shingles: repair | n/a X Yes | \$ | |
| | Shingles: Roof over existing | n/a X Yes | \$ | |
| | Shingles:Tear off & re-roof | n/a Yes X | Replace decking \$ | 2,000.00 |
| | Gutters/downspouts | n/a Yes X | 64' @\$7/ft. \$ | 448.00 |
| | Flashing | n/a X Yes | \$ | |
| | Eaves | n/a X Yes | \$ | |
| | Siding | n/a Yes X | Replace \$ | 1,600.00 |
| | Doors | n/a Yes X | Service & overhead \$ | 1,200.00 |
| | Windows | n/a Yes X | Replace 1 \$ | 200.00 |
| | Slab | n/a X Yes | \$ | |
| | Paint | n/a X Yes | \$ | |
| | Electrical | n/a X Yes | \$ | |
| | Other | n/a Yes | \$ | |
| Porches | Roof | n/a X Yes | \$ | |
| | Deck-upper | n/a Yes X | Replace \$ | 500.00 |
| | Decklower | n/a X Yes | \$ | |
| | Steps/handrails | n/a X Yes | \$ | |
| | Ceiling | n/a X Yes | \$ | |
| | Guardrails | n/a Yes X | Upper deck \$ | 400.00 |
| | Structural | n/a X Yes | \$ | |
| | Paint | n/a X Yes | \$ | |

n/a Yes

\$

Other

House

| Chimney | n/a | Yes X | Repairs | \$ 400.00 |
|------------------------------|-------|-------|----------------------------|----------------|
| Shingles: repair | n/a X | Yes | | \$ |
| Shingles: Roof over existing | n/a X | Yes | | \$ |
| Shingles:Tear off & re-roof | n/a X | Yes | | \$ |
| Gutters/downspouts | n/a | Yes X | Install 136' @ \$7/ft. | \$ 952.00 |
| Flashing | n/a X | Yes | | \$ |
| Eaves | n/a X | Yes | | \$ |
| Siding | n/a X | Yes 🗌 | | \$ |
| Storm Doors | n/a | Yes X | 3 - front/rear/upper deck | \$ 600.00 |
| Prime ("main") Doors | n/a | Yes X | 2 - front & rear | \$ 1,200.00 |
| Storm Windows | n/a | Yes X | Replace glass in 5 windows | \$ 100.00 |
| Prime ("main") Windows | n/a X | Yes | | \$ |
| Paint | n/a | Yes X | Window trim/overhang | \$ 500.00 |
| Foundation | n/a X | Yes | | \$ |
| Electrical | n/a X | Yes | | \$ |
| Other | n/a | Yes | | \$ |
| Other | n/a | Yes | | \$ |
| Other | n/a | Yes | | \$ |
| Other | n/a | Yes 🗌 | | \$ |

Exterior: Estimated Cost:* \$ 10,700.00
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

| Interior Co | ondition Report | | | | | | | |
|-------------|---|------|----|-----|-------------------------|----------------------------|----|--------|
| | Unit: Entire unit (single family) Upper unit of duplex | X | | | | Lower unit of duplex Other | | |
| Mechanical | Required Work | ш | | | | | | |
| Heating | Den sin/asalasa kailan | - /- | Ū. | V | | | Φ. | |
| | Repair/replace boiler | | X | Yes | Ш | | \$ | |
| | Repair radiation | | Χ | Yes | Ш | | \$ | |
| | Repair/replace furnace | n/a | Χ | Yes | Ш | | \$ | |
| | Repair ductwork | n/a | Χ | Yes | | | \$ | |
| | Replace thermostat | n/a | Χ | Yes | | | \$ | |
| | Repair/replace grilles | n/a | Х | Yes | | | \$ | |
| Electrical | Tune boiler/furn. insp ht exchang | €n/a | | Yes | Χ | Inspect/service | \$ | 200.00 |
| Liectrical | Repair/replace receptacles | n/a | Χ | Yes | | | \$ | |
| | Repair/replace switches | n/a | Χ | Yes | | | \$ | |
| | Repair/replace fixtures | n/a | | Yes | Χ | Upper hall/kitchen | \$ | 150.00 |
| | Install outlets and circuits | n/a | Χ | Yes | | | \$ | |
| | Install outlets and circuits | n/a | Х | Yes | | | \$ | |
| | Install outlets and circuits | n/a | Χ | Yes | | | \$ | |
| | Install outlets and circuits | n/a | Χ | Yes | | | \$ | |
| | Upgrade service | n/a | Х | Yes | | | \$ | |
| | Other | n/a | | Yes | | | \$ | |
| | Other | n/a | | Yes | | | \$ | |
| Plumbing | Repair/replace kitchen sink | n/a | x | Yes | | | \$ | |
| | Repair/replace kitchen sink fauce | | | Yes | $\overline{\mathbf{x}}$ | Replace | \$ | 75.00 |
| | | | X | Yes | | Теріаос | | 75.00 |
| | Repair/replace tub | | | | Н | | \$ | |
| | Repair/replace tub faucet | | X | Yes | Ш | | \$ | |
| | Repair/replace toilet | n/a | Х | Yes | Ц | | \$ | |
| | Repair/replace lavatory | n/a | | Yes | Χ | Replace | \$ | 100.00 |
| | Repair/replace lavatory faucet | n/a | | Yes | Χ | Replace | \$ | 50.00 |
| | Repair/replace wash tub | n/a | Χ | Yes | | | \$ | |
| | Repair/replace wash tub faucet | n/a | Χ | Yes | | | \$ | |
| | Unclog piping: | n/a | Χ | Yes | | | \$ | |
| | Repair drain/waste/vent piping | n/a | Х | Yes | | | \$ | |
| | Repair water piping | n/a | Χ | Yes | | | \$ | |
| | Repair/replace water heater | n/a | Χ | Yes | | | \$ | |
| | Other | n/a | | Yes | | | \$ | |
| | | | | | | | | |

\$

n/a Yes

Other

| Windows | | | | | |
|--------------|-------------------------------|---------------|------------------------------------|----|-----------|
| | Replace broken glass | n/a Yes X | 4 windows | \$ | 200.00 |
| | Repair or replace sash | n/a X Yes |] | \$ | |
| Doors | Repair or replace doors | n/a ☐ Yes 💢 | Bedroom door | \$ | 200.00 |
| | <u> </u> | | | | 200.00 |
| W-U-10-:::- | Repair or repl. locks/latches | n/a χ Yes | Self Help | \$ | |
| Walls/Ceilin | Repair or repl. @ defective | n/a Yes X | Kitchen/bath/basement stairway | \$ | 200.00 |
| Paint | Repair or repl. @ defective | n/a Yes 🔀 | Kitchen/bath/basement stairway | \$ | 800.00 |
| | Tropan of Topi. © defeetive | 1,44 100 X | Tatorior patti pacomoni otali way | Ψ | |
| Fire Safety | Install smoke alarm:bsmt. | n/a X Yes | Self Help | \$ | |
| | Install smoke alarm: 1st flr. | n/a X Yes | Self Help | \$ | |
| | Install smoke alarm: 2nd flr. | n/a X Yes | Self Help | \$ | |
| Handrails | Repair/replace defective | n/a Yes X | Self Help - Lower rail | \$ | 100.00 |
| Stairs | Repair defective | n/a X Yes | 1 | \$ | |
| Floors | | | | · | |
| Other | Repair defective | n/a Yes X | Kitchen floor | \$ | 900.00 |
| | | n/a Yes | | \$ | |
| | | n/a Yes |] | \$ | |
| | | n/a Yes |] | \$ | |
| | | n/a Yes | | \$ | |
| | | | Interior: Estimated Cost: | \$ | 2,975.00 |
| | | | Total Exterior and Interior Cost:* | \$ | 13,675.00 |
| | | | | | |

Prepared by: S. Denny/Inspected by: Paul Geboy Date: 4/8/2010

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway. If you will be occupying the home, you can get free lead-safe training from the Health Department! Call 286-5119 to schedule on-site training.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.